



Type A American Standard A-1, A-2, B-1, B-2 Spindle

	A5	A6	A8	A11	A15	A20
A-1	5¼	6½	8¼	11	15	20½
A-2*	3.2505	4.1880	5.50075	7.75075	11.251**	16.251**
A-3***	.5625	.625	.6875	.750	.8125	.875
A-4	2¼	2⅝	3⅜	4⅝	6½	9⅛
A-12	17/32	15/8	23/16	3¼	47/8	7¼
A-15	7/16-14	1/2-13	5/8-11	3/4-10	7/8-9	1-8

*Tolerance +.0005/-.000 **Tolerance +.001/-.000 ***Tolerance +.000/-.001

A-1 Has tapped holes on both the inner bolt circle and outer bolt circle.

A-2 Has tapped holes on the outer bolt circle, but has no hole on inner bolt circle.

B-1 Has drilled holes on the outer bolt circles, and has tapped holes on inner bolt circle.

B-2 Has drilled holes on the outer bolt circles, but has no holes on inner bolt circle.